



## Ayudantía 5 código G:

O2000;

(BROCA 9MM)

G00 Z200.;

X0.;

G28 U0. W0.;

T0101;

F0.25;

S4000;

#1=1;

IF[#1EQ0.] GOTO 10;

G00 Z10.;

G01 Z0.;

M98 P2001 L9;

G90;

G00 Z200.;

N10;

(TORNEADO CENTRADO)

G28 U0. W0.;

T0202;

F0.25;

S3000.;

G00 X30.;

Z10.;

G01 Z0.;

X62. Z-43.69

Z-56.69;(-13.)

G02 Z-80.69 R12.5;(-24.)

G01 Z-160.;

X200.;

Z-138.96;

X64.;

G01 X62.;

X54. Z-146.96;

Z-156.96;

G00 X200.;

Z200.;

(TRONZADO)

G00 Z200.;

X0.;

G28 U0. W0.;

T0303;

F0.12;

S1100;

G00 X200.;

Z-93.69;

X80.;

G0 X64.;

M98 P2002 L6;

G90;

G00 X200.;

Z-146.96;

G00 X64.;

G00 X-2.;

G00 X200.;

M30;

O2001;(PERFORACION)

G91;

G01 W-20.;

G01 W10.;

M99;

O2002;

G91;

G01 U-10.;

U10.;

W-6.;

M99;

